

VEHICLE INSPECTION REPORT

C356024

DON BUR BOX

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2013	VIN	SEPBV38GKDL061889	Brakes	Disc
Year	2013	Body Style	Trailer	Axle Combi	Tri
Mileage	TBC	Service history	Yes	Steering Combi	Front Lift
Fuel Type		Service documents	Printout	Rear Suspension	Air
Colour	RED	MOT Due	31/05/2026	Rear Doors	Roller

CORROSION BPW AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF

NSR

OSF

OSR

Spare

Photos





