

VEHICLE INSPECTION REPORT

C575176

KRAKER WALKING FLOOR

Inspection

Vehicle

| | |
|-----|----------|
| VAT | Plus VAT |
| V5 | N/A |

Details

| | | | | | |
|-----------|------------|------------|-------------------|-----------------|------|
| Reg. date | 01/01/2022 | Colour | WHITE | Brakes | Disc |
| Year | 2022 | VIN | XN1KRAKERN01Z0219 | Axle Combi | Tri |
| Mileage | TBC | Body Style | Trailer | Rear Suspension | Air |
| Fuel Type | | MOT Due | 31/05/2026 | Rear Doors | Barn |

SAF AXLES, FERRY LASHING RINGS, SERVICED & MAINTAINED BY VOLVO

Tyres

NSF

NSR

OSF

OSR

Spare

Photos





