

VEHICLE INSPECTION REPORT

YR68TGN

Ford Transit 350 2.0 TDCi 130ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	28/09/2018	VIN	WF0DXXTTGDJJ05566	CAP Below	£3,325.00
Year	2018	Body Style	Tipper	Gearbox	MANUAL
Mileage	116,686 Miles Warranted	MOT Due	18/03/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£4,925.00		
Colour	WHITE	CAP Average	£4,250.00		

AD-BLUE, TOW BAR

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Roof
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wing nsf
Scratched
Over 25mm Thru Paint




5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door Mirror Assy nsf
Broken
Replace



7: Door osf
Dented
With Paint Damage



8: C Post os
Chipped
Multiple Chips



9: Bumper Front
Scratched
Over 100mm Thru Paint



10: Bonnet
Scratched
Over 25mm Thru Paint




11: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



12: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



13: Door Pad osf
Soiled
Heavy



14: Seat Back Cover nsf
Soiled
Heavy



15: Carpets Front
Soiled
Heavy

Interior

Carpet Condition	Poor		Upholstery Condition	Poor
Seat Condition	Poor		Odour	No
Engine Runs	OK		No Excessive Smoking	OK
EML light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK			