

VEHICLE INSPECTION REPORT

YR68HYG

Ford Ranger Pick Up 2.2 TDCi XLT

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	06/09/2018	VIN	6FPPXXMJ2PJU88652	CAP Below	£4,275.00
Year	2018	Body Style	Pickup Double Cab	Gearbox	MANUAL
Mileage	121,375 Miles Warranted	MOT Due	28/08/2025	Gears	6
Fuel Type	Diesel	CAP Clean	£6,375.00		
Colour	WHITE	CAP Average	£5,450.00		

WARNING LIGHT ON DASH AD-BLUE, TWIN SIDE LOAD DOOR, E/MIRRORS, HEATED WINDSCREEN, TOW BAR, ALLOY WHEELS

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Bluetooth connection
- Air conditioning
- Central locking
- Cruise control
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Digital radio
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door nsr
Chipped
Edge Chip



3: Qtr Panel nsr
Dented
Over 30mm



4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Dented
With Paint Damage



6: Tailgate
Chipped
Multiple Chips



7: Door osf
Dented
Over 30mm



8: Wing osf
Dented
Over 30mm



9: Wing osf
Dented
Over 30mm




10: Screen Front
Chipped
Over 10mm



11: Carpets Rear
Soiled
Heavy



12: Door Pad nsr
Scuffed
Over 25mm



13: Seat Base Cover nsr
Torn
Over 3mm



14: Seat Base Cover osr
Soiled
Heavy



15: Door Pad osr
Scuffed
Over 25mm



16: Seat Base Cover osf
Torn
Over 3mm



17: Seat Base Cover nsf
Soiled
Heavy



18: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		