

VEHICLE INSPECTION REPORT

BP18JTZ

Mercedes-Benz Citan 109 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 12/06/2018

Year 2018

Mileage 90,269 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WDF4156032U243240

Body Style Panel Van SWB

CAP Clean £3,100.00

CAP Average £2,675.00

CAP Below £2,075.00

Gearbox MANUAL

SINGLE SIDE DOOR

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Park assist camera
- Front electric windows

Photos





Condition Check



Damage Photos



1: Screen Front
Chipped
UpTo 10mm



2: Door nsr
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK