

VEHICLE INSPECTION REPORT

YP67UXJ

Ford Transit Courier 1.5 TDCI 95PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	08/11/2017	VIN	WF0WXXTACWHC41769	CAP Below	£1,675.00
Year	2017	Body Style	Panel Van SWB	Gearbox	MANUAL
Mileage	140,514 Miles Warranted	MOT Due	07/11/2025	Gears	5
Fuel Type	Diesel	CAP Clean	£2,575.00		
Colour	WHITE	CAP Average	£2,200.00		

SINGLE SIDE DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Park assist camera
- Front electric windows

Photos





Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm




2: Bonnet
Chipped
Multiple Chips



3: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Not Thru Paint



4: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



5: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK