

VEHICLE INSPECTION REPORT

YS67MLL

Ford Transit Courier 1.5 TDCI 95PS

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Buyer To Apply		
Details					
Reg. date	16/01/2018	VIN	WF0WXXTACWHK51229	CAP Below	£2,300.00
Year	2018	Body Style	Panel Van SWB	Gearbox	MANUAL
Mileage	98,490 Miles	MOT Due	15/01/2026	Gears	5
	Warranted	CAP Clean	£3,400.00		
Fuel Type	Diesel	CAP Average	£2,925.00		
Colour	WHITE				

SINGLE SIDE DOOR, E/MIRRORS

	,			
Tyres				
Tyres NSF				
NSR				
OSF				
OSR				
Spare				
-				

Features

Park assist camera

• Front electric windows

Photos
















Condition Check



Damage Photos




1: Screen Front Chipped UpTo 10mm



2: Bonnet Chipped Multiple Chips



3: Door Mirror Assy osf Scratched (Painted) Over 25mm Thru Paint



4: Qtr Panel osr Dented 2 Or Less UpTo 10mm

Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Odour	Average No	
Engine Runs		OK	Gearbox 1st and Revers	e Test	OK
Brakes		OK	Clutch Slip Test from Sta	atic	OK
Parking Brake		OK	Gearbox Static Gear Se	lection (engine running)	OK
			No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illumina	ted	OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illu	uminated	OK