

## VEHICLE INSPECTION REPORT

**BP68WUB**

### Ford Transit Connect 200 1.5 ECOBLUE 100PS

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT  
V5 Buyer To Apply

#### Details

Reg. date 16/01/2019

Year 2019

Mileage 93,905 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0RXXWPGRJG54058

Body Style Panel Van L1

MOT Due 15/01/2026

CAP Clean £4,100.00

CAP Average £3,550.00

CAP Below £2,875.00

Gearbox MANUAL

Gears 6

\*STARTER ISSUES\* SINGLE SIDE DOOR

#### Tyres

NSF

NSR

OSF


OSR

Spare

## Features

- Rear parking sensor
- Air conditioning
- Front electric windows


## Photos







## Condition Check



## Damage Photos



1: Wing of  
Scratched  
Over 25mm Not Thru Paint



2: Bonnet  
Chipped  
Multiple Chips



3: Panel Front  
Chipped  
Multiple Chips



4: Wing nsf  
Chipped  
Multiple Chips



5: Door nsf  
Chipped  
Edge Chip



6: Qtr Panel osr  
Dented  
With Paint Damage



7: Door osf  
Scratched  
UpTo 25mm Thru Paint



8: Screen Front  
Chipped  
UpTo 10mm



9: Other  
N/A  
N/A

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)		OK
			No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK