

VEHICLE INSPECTION REPORT

YO19YNW

Ford Transit Custom 280 2.0 TDCI 105PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 30/07/2019

Year 2019

Mileage 123,805 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0YXXTTGYJG13331

Body Style Panel Van L1

MOT Due 29/07/2025

CAP Clean £4,575.00

CAP Average £4,000.00

CAP Below £3,200.00

Gearbox MANUAL

Gears 6

SINGLE SIDE DOOR

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Park assist camera
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



3: Door Moulding nsf
Missing
Replace



4: Sill ns
Dented
Over 30mm



5: Qtr Panel nsr
Dented
With Paint Damage



6: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



7: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm



8: Door osr
Dented
With Paint Damage



9: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



10: Seat Base Cover osf
Holed
Over 3mm



11: Other
N/A
N/A

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK