

VEHICLE INSPECTION REPORT

YR69GCV

Ford Transit Custom 340 2.0 ECOBLUE 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 20/11/2019

Year 2019

Mileage 153,981 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0YXXTTGYKJ48591

Body Style Panel Van L2

MOT Due 04/12/2025

CAP Clean £3,950.00

CAP Average £3,475.00

CAP Below £2,750.00

Gearbox MANUAL

Gears 6

SINGLE SIDE DOOR

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Front parking sensor
- Rear parking sensor
- Front electric windows

Photos






Condition Check



Damage Photos



1: Screen Front
Chipped
UpTo 10mm



2: Other
N/A
N/A



3: Bonnet
Chipped
Multiple Chips



4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Other
N/A
N/A



6: Door nsf
Chipped
Edge Chip



7: Sill ns
Rusted
Over 5mm



8: Fuel Flap
Missing
Replace



9: Door nsr
Dented
2 Or Less UpTo 10mm



10: Door nsr
Dented
With Paint Damage



11: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm



12: Door nsr
Dented
With Paint Damage



13: Door osr
Dented
With Paint Damage



14: Sill os
Dented
With Paint Damage



15: Qtr Panel osr
Dented
With Paint Damage



16: Door osf
Dented
Over 2 UpTo 10mm



17: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK