

# VEHICLE INSPECTION REPORT

**YS65GUC**

## Ford Transit Connect 240 1.6 TDCI 95PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT  
V5 Buyer To Apply

### Details

Reg. date 11/12/2015

Year 2015

Mileage 106,986 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0SXXWPGSFJ74925

Body Style Panel Van L2

MOT Due 25/10/2025

CAP Clean £2,850.00

CAP Average £2,350.00

CAP Below £1,675.00

Gearbox MANUAL

Gears 5

### SIDE LOADING DOOR

### Tyres

NSF

NSR

OSF


OSR

Spare

## Features

- Park assist camera
- Front electric windows


## Photos







## Condition Check



## Damage Photos



1: Wing of  
Dented  
Over 30mm



2: Bonnet  
Chipped  
Multiple Chips




3: Bumper Front  
Dented  
Between 10mm + 30mm



4: Other  
N/A  
N/A



5: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



6: Wing nsf  
Dented  
Between 10mm + 30mm



7: Door nsf  
Dented  
Between 10mm + 30mm



8: Door nsr  
Chipped  
Multiple Chips





9: Qtr Panel nsr  
Chipped  
Multiple Chips



10: Qtr Panel nsr  
Dented  
With Paint Damage



11: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



12: Qtr Panel Trim ns  
Scuffed  
Over 25mm



13: Other  
N/A  
N/A



14: Door osr  
Hole  
UpTo 10mm



15: Other  
N/A  
N/A



16: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



17: Qtr Panel Moulding os  
Scuffed (Unpainted)  
Over 100mm



18: Door osf  
Dented  
2 Or Less UpTo 10mm



19: Carpets Front  
Holed  
Over 3mm



20: Other  
N/A  
N/A

## Interior

<b>Carpet Condition</b>	<b>Average</b>	<b>Upholstery Condition</b>	<b>Average</b>
<b>Seat Condition</b>	<b>Average</b>	<b>Odour</b>	<b>No</b>
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK