

VEHICLE INSPECTION REPORT

YS18BVK

Ford Transit Connect 220 1.5 TDCI 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	06/08/2018	Colour	WHITE	CAP Average	£2,525.00
Year	2018	VIN	WF0RXXWPGRHE20069	CAP Below	£1,975.00
Mileage	126,995 Miles Warranted	Body Style	Panel Van L1	Gearbox	MANUAL
Fuel Type	Diesel	CAP Clean	£2,925.00	Gears	5

SIDE LOADING DOOR

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing of
Dented
Over 30mm



2: Other
N/A
N/A



3: Other
N/A
N/A



4: Screen Front
Chipped
Over 10mm



5: Wing nsf
Dented
Over 2 UpTo 10mm



6: Qtr Panel osr
Dented
With Paint Damage



7: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



8: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



9: Carpets Front
Holed
Over 3mm

10: Other
N/A
N/A

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	