

# VEHICLE INSPECTION REPORT

**SP11UXV**

## Ford Transit Medium Roof Van TDCi 115ps

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date	30/03/2011	Body Style	Crew Van	Gearbox	MANUAL
Year	2011	Keys	2	Gears	6
Mileage	76,849 Miles Warranted	MOT Due	07/03/2026	Doors	2
Fuel Type	Diesel	CAP Clean	£1,625.00	Steering Combi	Steer
Colour	WHITE	CAP Average	£1,275.00	Rear Suspension	Steel
VIN	WF0XXXTTFXAT17505	CAP Below	£850.00		

### Tyres

NSF

NSR

OSF


OSR

Spare

## Features

- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Seat Base Cover osf  
Torn  
Over 3mm



2: Sill os  
Rusted  
Over 5mm



3: Roof  
Rusted  
Over 5mm



4: Bonnet  
Rusted  
Over 5mm



5: Wing osf  
Poor Previous Repair  
Poor Paint



6: Door osf  
Rusted  
Over 5mm



7: B Post os  
Rusted  
Over 5mm



8: Qtr Panel osr  
Rusted  
Over 5mm





9: D Post os  
Dented  
With Paint Damage



10: Tailgate  
Dented  
With Paint Damage



11: Qtr Panel osr  
Rusted  
Over 5mm



12: Door nsr  
Dented  
Over 30mm



13: B Post ns  
Rusted  
Over 5mm



14: Door nsf  
Dented  
Over 30mm



15: Wing nsf  
Poor Previous Repair  
Poor Paint

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK
Windows		OK	Radio		OK
			Steering		OK