

VEHICLE INSPECTION REPORT

ST61LFX

Ford Transit T300 2.2 TDCi 100ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 29/12/2011

Year 2011

Mileage 149,857 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0XXXTTFXBU65438

Body Style Panel Van LWB

Keys 2

MOT Due 04/03/2026

CAP Clean £930.00

CAP Average £730.00

CAP Below £475.00

Gearbox MANUAL

Gears 6

Doors 2

Steering Combi Steer

Rear Suspension Steel

SINGLE SIDE DOOR

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Centre Console Front
Holed
Over 3mm



2: Roof
Rusted
Over 5mm

No Image



3: Bonnet
Rusted
Over 5mm

4: Wing osf
Rusted
Over 5mm



5: Wing of
Rusted
Over 5mm



6: Door osf
Rusted
Over 5mm



7: B Post os
Rusted
Over 5mm



8: Qtr Panel osr
Rusted
Over 5mm



9: Tailgate
Rusted
Over 5mm



10: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



11: Qtr Panel nsr
Rusted
Over 5mm



12: Door nsr
Dented
Over 30mm



13: B Post ns
Rusted
Over 5mm



14: Door nsf
Dented
Over 30mm



15: Wing nsf
Dented
With Paint Damage

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK