

# VEHICLE INSPECTION REPORT

**ST61NDK**

## Ford Transit Connect T200 1.8 TDCi 75ps

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date	29/12/2011	Body Style	Panel Van SWB	Gearbox	MANUAL
Year	2011	Keys	2	Gears	5
Mileage	94,723 Miles Warranted	MOT Due	03/12/2025	Doors	2
Fuel Type	Diesel	CAP Clean	£1,075.00	Steering Combi	Steer
Colour	WHITE	CAP Average	£830.00	Rear Suspension	Steel
VIN	WF0TXXTPTBU75442	CAP Below	£575.00		

### Tyres

NSF

NSR

OSF



OSR



Spare

## Features

- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Sill os  
Rusted  
Over 5mm



2: Bonnet  
Dented  
Over 30mm



3: Door osf  
Dented  
Between 10mm + 30mm



4: Qtr Panel osr  
Dented  
Between 10mm + 30mm



5: Bumper Rear Moulding  
Scuffed (Unpainted)  
UpTo 100mm



6: Tailgate  
Chipped  
1 To 5



7: Qtr Panel nsr  
Dented  
Over 30mm



8: Sill ns  
Dented  
Over 30mm



9: Door nsf  
Dented  
Between 10mm + 30mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK