

VEHICLE INSPECTION REPORT

PJ15VXM

Iveco Daily 2.3 High Roof Van 3520 WB

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 01/07/2015

Year 2015

Mileage 200,689 miles Not Warranted

Fuel Type Diesel

Colour White

VIN ZCFC1357X05033634

Body Style Panel Van

MOT Due 21/05/2025

CAP Clean £2,500.00

CAP Average £2,050.00

CAP Below £1,475.00

Gearbox MANUAL

BEDFORD SIDE LOADING DOOR, TOW BAR, E/WINDOWS

Tyres

NSF

NSR

OSF

OSR


Spare

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wing nsf
Dented
Over 30mm



3: Bumper Front Grill
Missing
Replace



4: Door Mirror Assy nsf
Missing
Replace



5: Qtr Panel nsr
Dented
With Paint Damage



6: Sill ns
Cracked
Replace



7: Panel Rear
Cracked
Replace



8: Sill os
Cracked
Replace



9: Wing osf
Dented
Over 30mm



10: Door Mirror Assy osf
Broken
Replace



11: Carpets Front
Torn
Over 10mm

Interior

Carpet Condition	Poor	Upholstery Condition	Average
Seat Condition	Average	Odour	No