

# VEHICLE INSPECTION REPORT

**VX16AEG**

## Dennis Elite 6

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 11/04/2016

Year 2016

Mileage 74,331 Km Warranted

Fuel Type Diesel

Colour WHITE

VIN SEG2628HR6BG21601

Body Style Refuse Collector

Cab Type CREW CAB

Gearbox AUTOMATIC

Axle Combi 6x2

\*WARNING LIGHT ON DASH\* OLYMPUS TP22 BODY, TERBERG SPLIT LIFT

### Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4


## Features

- Park assist camera

## Photos










## Condition Check



## Damage Photos



1: Bonnet  
Poor Previous Repair  
Poor Colour



2: Bonnet  
Poor Previous Repair  
Poor Colour



3: Other  
N/A  
N/A



4: Other  
N/A  
N/A



5: Other  
N/A  
N/A



6: Bumper Rear  
Rusted  
Over 5mm



7: Door osf  
Chipped  
Edge Chip



8: Door Mirror Assy osf  
Scuffed (Unpainted)  
Over 100mm



9: Seat Base Cover osf  
Torn  
Over 3mm



10: Seat Back Cover osf  
Torn  
Over 3mm



11: Seat Base Cover nsf  
Torn  
Over 3mm



12: Seat Base Cover nsf  
Torn  
Over 3mm

## Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Parking Brake	OK			Gearbox Static Gear Selection (engine running)	OK		
				No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		