

VEHICLE INSPECTION REPORT

YJ17FEG

Peugeot Boxer 435 2.0 BLUE HDI 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 05/06/2017

Year 2017

Mileage 166,077 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN VF3YD2MFC12D07935

Body Style Ambulance

MOT Due 30/05/2026

CAP Clean £3,600.00

CAP Average £3,025.00

CAP Below £2,300.00

Gearbox MANUAL

Gears 6

SINGLE SIDE DOOR, E.MIRRORS, FERNO PEGASUS STRETCHER (YEAR 2017)

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Navigation system
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 25mm Not Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
Over 10mm



4: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



6: Qtr Panel nsr
Dented
With Paint Damage



7: Sill os
Dented
With Paint Damage



8: Door osf
Scratched
Over 25mm Thru Paint



9: Moulding of Wing
Broken
Replace

Interior

| Carpet Condition | | Average | Upholstery Condition | | Average |
|--------------------------|--|---------|--|--|---------|
| Seat Condition | | Average | Odour | | No |
| Engine Runs | | OK | Gearbox 1st and Reverse Test | | OK |
| Brakes | | OK | Clutch Slip Test from Static | | OK |
| Parking Brake | | OK | Gearbox Static Gear Selection (engine running) | | OK |
| | | | No Excessive Smoking | | OK |
| EML light illuminated | | OK | Oil warning light illuminated | | OK |
| Airbag light illuminated | | OK | DPF light illuminated | | OK |
| ABS light illuminated | | OK | Service indicator light illuminated | | OK |