

VEHICLE INSPECTION REPORT

YJ17FHG

Peugeot Boxer 2.0 BLUE HDI 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 05/06/2017

Year 2017

Mileage 153,035 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN VF3YD2MFC12D11702

Body Style Ambulance

MOT Due 17/05/2026

CAP Clean £3,825.00

CAP Average £3,225.00

CAP Below £2,475.00

Gearbox MANUAL

Gears 6

SINGLE SIDE DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR



Spare

Features


- Navigation system
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing Front Arch Extension os
Broken
Replace



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
 Scratched
 Over 25mm Not Thru Paint



4: Qtr Panel Arch Extension ns
 Scuffed (Unpainted)
 Over 100mm



5: Qtr Panel Arch Extension os
 Scuffed (Unpainted)
 Over 100mm



6: Other
 N/A
 N/A



7: Qtr Panel osr
 Dented
 With Paint Damage

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK