

VEHICLE INSPECTION REPORT

YJ17FDY

Peugeot Boxer 2.0 BLUE HDI 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 05/06/2017

Year 2017

Mileage 152,265 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN VF3YD2MFC12D04230

Body Style Ambulance

MOT Due 23/05/2026

CAP Clean £3,825.00

CAP Average £3,225.00

CAP Below £2,475.00

Gearbox MANUAL

Gears 6

SINGLE SIDE DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR




Spare

Features


- Navigation system
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
Edge Chip



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
UpTo 10mm



4: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



6: Door nsr
Dented
With Paint Damage



7: Door nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



9: Panel Rear
Dented
With Paint Damage



10: Panel Rear
Dented
With Paint Damage



11: Qtr Panel osr
Dented
With Paint Damage



12: Moulding osf Wing
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	