

VEHICLE INSPECTION REPORT

LV22USP

RENAULT MASTER 35 L1H2

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 13/07/2022

Year 2022

Mileage 66,502 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN VF6VG000969045498

Body Style Curtainside L1

MOT Due 12/07/2025

Gearbox MANUAL

Gears 6

Tail Lift Column

WARNING LIGHT ON DASH E/MIRRORS

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Other
N/A
N/A



3: Bumper Front
Cracked
Over 25mm



4: Wing nsf
Dented
Over 30% Of Panel



5: Wing nsf
Dented
With Paint Damage



6: Seat Base Cover osf
Soiled
Heavy



7: Other
N/A
N/A

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault