

VEHICLE INSPECTION REPORT

YJ17FEO

Peugeot Boxer 435 2.0 BLUE HDI 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 05/06/2017

Year 2017

Mileage 141,784 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN VF3YD2MFC12D10385

Body Style Ambulance

MOT Due 11/05/2026

Gearbox MANUAL

Gears 6

SIDE LOADING DOOR, E/MIRRORS, FERNO PEGASUS STRETCHER (YEAR 2017)

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Navigation system
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 25mm Not Thru Paint



2: Bumper Front
Dented
Between 10mm + 30mm



3: Grille Front
Broken
Replace




4: Bonnet
Chipped
Multiple Chips



5: Screen Front
Chipped
UpTo 10mm



6: Moulding nsf Wing
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel osr
Dented
Over 30% Of Panel



8: Qtr Panel Arch Extension os
Scuffed (Unpainted)
Over 100mm



9: Sill os
Rusted
Over 5mm



10: Steering Wheel
Damaged
Replace



11: Other
N/A
N/A



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		No	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Parking Brake		OK		Gearbox Static Gear Selection (engine running)		OK	
				No Excessive Smoking		OK	
EML light illuminated		OK		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		OK	