

VEHICLE INSPECTION REPORT

YJ17FHK

Peugeot Boxer 435 2.0 BLUE HDI 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 05/06/2017

Year 2017

Mileage 162,842 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN VF3YD2MFC12D11052

Body Style Ambulance

MOT Due 08/05/2026

CAP Clean £3,600.00

CAP Average £3,075.00

CAP Below £2,350.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH FERGO PEGASUS STRETCHER (YEAR 2017), SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare


Features

- Navigation system
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos



Condition Check



Damage Photos



1: Wing osf
Chipped
Multiple Chips



2: Bonnet
Dented
2 Or Less UpTo 10mm



3: Bumper Front
Scratched
Over 25mm Not Thru Paint



4: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



6: Qtr Panel nsr
Rusted
Over 5mm



7: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



8: Qtr Panel osr
Chipped
Edge Chip



9: Door osf
Dented
With Paint Damage



10: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



11: Other
N/A
N/A



12: Other
N/A
N/A

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK