

## VEHICLE INSPECTION REPORT

**YJ17FHP**

### Peugeot Boxer 435 2.0 BLUE HDI 130PS

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 Present

#### Details

Reg. date 05/06/2017

Year 2017

Mileage 143,590 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN VF3YD2MFC12D12910

Body Style Ambulance

MOT Due 15/05/2026

CAP Clean £4,000.00

CAP Average £3,425.00

CAP Below £2,625.00

Gearbox MANUAL

Gears 6

SINGLE SIDE DOOR, E/MIRRORS, FERNO PEGASUS STRETCHER (YEAR 2017)

#### Tyres

NSF

NSR

OSF


OSR

Spare

### Features

- Navigation system
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows


### Photos







## Condition Check



## Damage Photos



1: Screen Front  
Chipped  
Over 10mm



2: Moulding nsf Wing  
Scuffed (Unpainted)  
Over 100mm





3: Qtr Panel nsr  
Dented  
Over 30mm



4: Qtr Panel nsr  
Dented  
Over 30mm



5: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
Over 100mm



6: Qtr Panel osr  
Dented  
With Paint Damage



7: Other  
N/A  
N/A

**Interior**

<b>Carpet Condition</b>	<b>Average</b>	<b>Upholstery Condition</b>	<b>Average</b>
<b>Seat Condition</b>	<b>Average</b>	<b>Odour</b>	<b>No</b>
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK