

# VEHICLE INSPECTION REPORT

**YH67HYK**

## IVECO DAILY 72-180

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 03/11/2017

VIN ZCFC170D10D576798

Gearbox MANUAL

Year 2017

Body Style Flatbed

Axle Combi 4x2

Mileage 76,380 Km Warranted

CAP Clean £9,100.00

Rear Suspension Steel

Fuel Type Diesel

CAP Average £7,725.00

Colour WHITE

CAP Below £5,850.00

\*MOT HISTORY INCORRECTLY RECORDED IN KM/MILES, VEHICLE BEEN STOOD A WHILE\* WINCH, RAMPS

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Dented  
Over 30mm



2: Bonnet  
Chipped  
Multiple Chips





3: Bumper Front  
Cracked  
Over 25mm



4: Door osf  
Chipped  
Multiple Chips



5: Seat Base Cover osf  
Soiled  
Light



6: Seat Base Cover nsf  
Soiled  
Heavy

**Interior**

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	OK
<b>Seat Condition</b>	Poor	<b>Odour</b>	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		