

VEHICLE INSPECTION REPORT

WV23RCF

Renault Master LL35 DCI 145PS BUSINESS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 13/04/2023

Year 2023

Mileage 159,727 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN VF1VA000970045739

Body Style Luton

MOT Due 12/04/2026

CAP Clean £12,900.00

CAP Average £12,250.00

CAP Below £10,750.00

Gearbox MANUAL

WARNING LIGHT ON DASH, CRACKED WINDSCREEN AD-BLUE, E/MIRRORS, HEATED SEATS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Digital radio
- Central locking
- Cruise control
- Air conditioning
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Auxiliary input socket
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Fuel Flap
Cracked
Replace



3: Qtr Panel Trim ns
Broken
Replace



4: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



6: Qtr Panel Trim os
Broken
Replace



7: Qtr Panel Trim os
Broken
Replace



8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



10: Wing osf
Scratched
Over 25mm Not Thru Paint



11: Wing osf
Scratched
Over 25mm Not Thru Paint



12: Screen Front
Cracked
Replace



13: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault