

VEHICLE INSPECTION REPORT

PE68VPL

Daf LF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 15/10/2018

Colour BLUE

Cab Type DAY CAB

Year 2018

VIN XLRAEL3700L471965

Gearbox MANUAL

Mileage 425,040 Km Warranted

Body Style Beavertail

Axle Combi 4x2

Fuel Type Diesel

MOT Due 30/09/2025


Rear Suspension Steel

WARNING LIGHT ON DASH SERVICE SCHEDULE LIST AVAILABLE, SURROUND CAMERA SYSTEM, WINCH

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint



2: Bumper Front
Cracked
Over 25mm



3: Other
N/A
N/A



4: Other
N/A
N/A



5: Screen Front
Chipped
UpTo 10mm



6: Bumper Front
Dented
With Paint Damage



7: Other
N/A
N/A



8: Door Mirror Assy nsf
Broken
Replace



9: Other
N/A
N/A



10: Bumper Rear
Rusted
Over 5mm



11: Other
N/A
N/A



12: Other
N/A
N/A



13: Door Mirror Assy osf
Broken
Replace

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	