

VEHICLE INSPECTION REPORT

LN13DWE

MERCEDES-BENZ ATEGO 1022

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	29/08/2013	VIN	WDB9700452L733833	Gearbox	MANUAL
Year	2013	Body Style	Box Van	Axle Combi	4x2
Mileage	287,758 Km Warranted	Service history	Yes	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	30/04/2026	Rear Doors	Roller
Colour	WHITE	Cab Type	DAY CAB	Tail Lift	Column

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



