

VEHICLE INSPECTION REPORT



Man TGS 26.360

Inspection	Vehicle		
Serious Damage? No	VAT	Plus VAT	
	V5	Present	

Details					
Reg. date	27/10/2016	VIN	WMA18SZZ5GP073752	Axle Combi	6x2
Year	2016	Body Style	Curtainside	Steering Combi	Rear-Lift Steer
Mileage	407,440 Km Warranted	MOT Due	30/11/2025	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	DAY CAB	Rear Doors	Barn
Colour	BLUE	Gearbox	MANUAL		

WARNING LIGHT ON DASH FORK LIFT BRACKET, SERVICE SCHEDULE LIST AVAILABLE

Tyres					
NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OS01	OSO2	OSO3	0SO4	

Features

 Cruise control 	Radio/CD	 Front electric windows 	 Cloth seat trim
------------------------------------	----------	--	-------------------------------------

Photos














































Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips

2: Panel Front Scratched Over 25mm Thru Paint







4: Bumper Front Hole Over 25mm



5: Bumper Front Scratched Over 100mm Thru Paint



6: Door nsf Scratched Over 25mm Thru Paint



7: Door nsf Scratched Over 25mm Thru Paint

Interior



8: Wing osf Scratched Over 25mm Thru Paint

Carpet Condition Seat Condition	OK OK		Upholstery Condition Odour	ОК -	
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		ОК			