

VEHICLE INSPECTION REPORT

LT66LAE

Ford Transit Courier 1.5 TDCI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 18/11/2016

VIN WF0WXXTACWGL62359

CAP Below £1,225.00

Year 2016

Body Style Panel Van

Gearbox MANUAL

Mileage 141,928 Miles
Warranted

MOT Due 18/11/2025

Gears 5

Fuel Type Diesel

CAP Clean £1,950.00

Colour GREEN

CAP Average £1,650.00

WARNING LIGHT ON DASH SINGLE SIDE DOOR

Tyres

NSF


NSR

OSF


OSR

Spare

Photos



Condition Check



Damage Photos



1: Wing osf
Dented
Over 2 UpTo 10mm



2: Wing osf
Scratched
UpTo 25mm Thru Paint



3: Bonnet
Chipped
Multiple Chips



4: Other
N/A
N/A



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Chipped
1 To 5



7: Door nsr
Chipped
Multiple Chips



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel Trim ns
Scuffed
Over 25mm



10: Door nsr
Chipped
1 To 5



11: Bumper Rear
Scratched
Over 25mm Not Thru Paint



12: Qtr Panel osr
Dented
Over 30mm



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK