

VEHICLE INSPECTION REPORT

001622

HAMM HD8

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2013	Fuel Type	Diesel	Body Style	ROLLER
Year	2013	Colour		Gearbox	Hydrostatic
Mileage	1,463 Hours Not Warranted	VIN	H1991590	Axle Combi	Tandem

COLLECT FROM PRESTON ROLL BAR, VIBRATING ROLLER, PLATE UNREADABLE

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



