

VEHICLE INSPECTION REPORT

001407

HAMM HD12

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2013	Fuel Type	Diesel	Body Style	ROLLER
Year	2013	Colour		Gearbox	Hydrostatic
Mileage	1,568 Hours Not Warranted	VIN	H2003773	Axle Combi	Tandem

COLLECTION FROM PRESTON ROLL BAR, VIBRATING ROLLER NO PLATE

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



