

# VEHICLE INSPECTION REPORT

**YP68VTY**

## Ford Transit 350 2.0 TDCi 105PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 15/11/2018

Year 2018

Mileage 31,837 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0XXXTTGXJB16748

Body Style Panel Van L2

MOT Due 30/10/2025

CAP Clean £7,450.00

CAP Average £6,425.00

CAP Below £5,025.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOAD DOOR, ROOF RACK, ARMOURGARD TOOL VAULT

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Bluetooth connection
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

## Photos












## Condition Check



## Damage Photos



1: Wing nsf  
Dented  
Over 30mm



2: Wing Front Arch Extension ns  
Scuffed (Unpainted)  
Over 100mm



3: Door Moulding nsf  
Scuffed (Unpainted)  
Over 100mm



4: Door nsf  
Dented  
Over 30mm



5: Door Moulding nsf  
Scuffed (Unpainted)  
Over 100mm



6: Qtr Panel nsr  
Dented  
Over 30mm



7: Qtr Panel nsr  
Dented  
Over 30mm



8: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
Over 100mm



9: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
Over 100mm



10: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



11: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
Over 100mm



12: Door nsr  
Dented  
Over 30mm



13: Roof  
Dented  
With Paint Damage



14: Door osr  
Dented  
Over 30mm





15: Qtr Panel osr  
Dented  
With Paint Damage



16: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



17: Door osf  
Scratched  
Over 25mm Thru Paint



18: Door Pad osf  
Soiled  
Heavy

## Interior

**Carpet Condition** OK  
**Seat Condition** OK

**Upholstery Condition** Poor  
**Odour** -

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		