

# VEHICLE INSPECTION REPORT

**KR18XME**

## Daf XF 530

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 24/05/2018

Year 2018

Mileage 804,000 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRTGH4300G209627

Body Style Tractor Unit

MOT Due 30/04/2026

Cab Type SUPER SPACE CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lif Steert

Rear Suspension Air

SLIDING 5TH WHEEL

### Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4

## Features

- Cruise control
- Digital radio
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


## Photos












## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Chipped  
Multiple Chips





3: Panel Front  
Scratched  
Over 25mm Thru Paint



4: Qtr Panel Trim os  
Broken  
Replace



5: Door osf  
Chipped  
Multiple Chips



6: Door osf  
Scratched  
Over 25mm Thru Paint



7: Seat Base Cover osf  
Holed  
Over 3mm

## Interior

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	OK
<b>Seat Condition</b>	Poor	<b>Odour</b>	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		