

VEHICLE INSPECTION REPORT

100047

KRONE CURTAINSIDE EUROLINER

| Inspection | Vehicle |
|------------|---------|
| | |

| VAT | Plus VAT |
|-----|----------|
| V5 | N/A |

Details

| Reg. date | 01/01/2013 | Fuel Type | | Body Style | Trailer |
|-----------|------------|-----------|-------------------|------------|---------|
| Year | 2013 | Colour | | Brakes | Drum |
| Mileage | TBC | VIN | WKESD000000599657 | Axle Combi | Tri |

NOT REGISTERED IN THE UK 13.9M, BPW AXLES, ENXL RATED HEADBOARD, RAISE & LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF

NSR

OSF OSR

Spare

Photos















