

# VEHICLE INSPECTION REPORT

**YH24MBP**

## PEUGEOT EXPERT 1000 100kW 75kWh Professional Crew Van Auto

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Buyer To Apply

### Details

Reg. date 16/08/2024

Year 2024

Mileage 14,939 Miles Not Warranted

Fuel Type Electric

Colour WHITE

VIN VF3V1ZKXZNZ072365

Body Style Panel Van

MOT Due 15/08/2027

Gearbox AUTOMATIC

Gears 1

CHARGING LEADS PRESENT, E/MIRRORS, TWIN LOADING DOORS

### Tyres

NSF

NSR

OSF

OSR


Spare

## Features

- Air conditioning
- Front electric windows


## Photos







## Condition Check



## Damage Photos



1: Other  
N/A  
N/A



2: Bumper Front  
Insecure  
Action Required



3: Door nsf  
Chipped  
1 To 5

4: Door nsr  
Dented  
Between 10mm + 30mm

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		OK	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	