

VEHICLE INSPECTION REPORT

185,716 Km Warranted

Diesel

DG66RZT

Man TGM 18.250

Serious Damage?	No	VAT	Plus VAT		
		V5	Present		
Details					
Reg. date	10/11/2016	Colour	BLUE	Cab Type	DAY CAB
Year	2016	VIN	WMAN08ZZ5HY350438	Gearbox	MANUAL

HMF 1430 L1 REMOTE CRANE (YEAR 2016), SERVICE SCHEDULE LIST AVAILABLE

Body Style

MOT Due

Vehicle

1	v	r	Δ	c
•	y	•	·	•

Mileage

Fuel Type

Inspection

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OSO1	OSO2	OSO3	OSO4	

Features

- Cruise controlCloth seat trim
- Digital radio
- Radio/CD

Dropside & Crane

30/11/2025

Axle Combi

Rear Suspension

Front electric windows

4x2

Steel

Photos

































Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Bumper Front Moulding Scuffed (Unpainted) Over 100mm



3: Door nsf Scratched Over 25mm Thru Paint



4: Wing nsf Scratched Over 25mm Thru Paint



5: Qtr Panel Moulding os Broken Replace



6: Wing osf Scratched Over 25mm Thru Paint



7: Door osf Scratched Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upho	olstery Condition OK	
Seat Condition	OK	Odou	ır -	
Engine Runs		OK No I	Excessive Smoking	OK
EML light illuminated		OK DPF	= light illuminated	OK
ABS light illuminated		OK		