

VEHICLE INSPECTION REPORT

EY12YFK

SCANIA P 360

Inspection

Vehicle

| | |
|-----|----------------|
| VAT | Plus VAT |
| V5 | Buyer To Apply |

Details

| | | | | | |
|-----------|--------------------------|------------|-------------------|-----------------|--------|
| Reg. date | 01/05/2012 | Colour | RED | Gearbox | MANUAL |
| Year | 2012 | VIN | VLUP8X40009166321 | Axle Combi | 8x4 |
| Mileage | 515,856 Km Not Warranted | Body Style | Tipper | Rear Suspension | Steel |
| Fuel Type | DIESEL | Cab Type | DAY CAB | | |

*NO PARKING BRAKE**WARNING LIGHT ON DASH* ALLOY BODY TIPPING GEAR, SHEETING SYSTEM, WEIGH SYSTEM, SURROUND CAMERA SYSTEM

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Park assist camera

Photos





