

VEHICLE INSPECTION REPORT

SF58FLB

SCANIA p 230

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	01/09/2008	Colour	YELLOW	Gearbox	MANUAL
Year	2008	VIN	5209051	Axle Combi	4x2
Mileage	279,057 Km Not Warranted	Body Style	Sweeper	Rear Suspension	Steel
Fuel Type	Diesel	Cab Type	DAY CAB		

AIR LEAK IN CAB JOHNSTON VT650 BODY, 9813 BRUSH HOURS

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Park assist camera

Photos





