

## VEHICLE INSPECTION REPORT

**PF18PZT**

### Fiat Doblo CARGO 16V 1.3 MULTIJET 95PS

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 Present

#### Details

Reg. date 05/07/2018

Year 2018

Mileage 45,048 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006L05572

Body Style Panel Van L1

MOT Due 07/07/2026

CAP Clean £3,750.00

CAP Average £3,225.00

CAP Below £2,500.00

Gearbox MANUAL

Gears 5

SIDE LOAD DOOR, TOW BAR

#### Tyres

NSF

NSR

OSF


OSR

Spare



## Features

- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

## Photos












Condition Check



Damage Photos



1: Wing nsf  
Dented  
Over 30mm



2: Screen Front  
Chipped  
Over 10mm

Interior

Carpets Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK

EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		