

VEHICLE INSPECTION REPORT

C294213

DON BUR CURTAINSIDE DOUBLE DECK STEPFRAME

Inspection	Vehicle
------------	---------

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2009	Colour	BLUE	Axle Combi	Tri
Year	2009	VIN	L055906	Rear Suspension	Air
Mileage	TBC	Body Style	Trailer	Rear Doors	Barn
Fuel Type		Brakes	Drum		

BPW AXLES, FERRY LASHING RINGS, ENXL RATED CURTAINS

Tyres

NSF

NSR

OSF

OSR

Spare

Photos













