

VEHICLE INSPECTION REPORT

C70574

KUBOTA U17-3

Inspection

Vehicle

VAT

V5

Not Present

Details

3 BUCKETS

Reg. date

2019

Fuel Type

Colour

Body Style

MINI EXCAVATOR

Mileage

724 Hours Not
Warranted

VIN

KBCUO173PK3C70574

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



