

## **VEHICLE INSPECTION REPORT**



### **VOLKSWAGEN CADDY C20 1.9 TDI PD 104PS**

| Inspection | Vehicle |                |  |
|------------|---------|----------------|--|
|            | VAT     | Plus VAT       |  |
|            | V5      | Buyer To Apply |  |
| Details    |         |                |  |

| Reg. date | 29/06/2006  | Colour     | SILVER            | Gearbox | AUTOMATIC |
|-----------|-------------|------------|-------------------|---------|-----------|
| Year      | 2006        | VIN        | WV1ZZZ2KZ6X092110 | Gears   | 6         |
| Mileage   | Not Showing | Body Style | Panel Van         |         |           |
| Fuel Type | Diesel      | MOT Due    | Expired           |         |           |

# \*ENGINE NOISE\* SIDE LOAD DOOR, E/ MIRRORS, ROOF RACK, HEATED WINDSCREEN, DEADLOCKS (WITH KEYS)

| Tyres<br>NSF |  |  |
|--------------|--|--|
|              |  |  |
| NSR          |  |  |
| OSF          |  |  |
| OSR          |  |  |
| Spare        |  |  |

### **Features**

Rear parking sensor

• Central locking

#### Photos



