

VEHICLE INSPECTION REPORT

60302

KUBOTA L4240

Inspection	Vehicle	Vehicle		
	VAT	Plus VAT		
	V5	N/A		

Details

Reg. date		Fuel Type	Diesel	Body Style	Agricultural Tractor	
Year		Colour		Gearbox	Manual	
Mileage	2,194 Hours Warranted	VIN	L420060302	Axle Combi	\$WD	

8X8 SHUTTLE TRANS

iyies

NSF

NSR

OSF OSR

Spare

Photos









