

# VEHICLE INSPECTION REPORT

**PE17HWA**

## Daf LF 150

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date	16/03/2017	VIN	XLRAEL1500L463451	Cab Type	DAY CAB
Year	2017	Body Style	Box Van	Gearbox	MANUAL
Mileage	734,757 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Printout	Rear Suspension	Steel
Colour	RED	MOT Due	31/10/2025	Tail Lift	Cantilever

\*COLLECTED AS NON RUNNER - TAIL LIFT ISSUE\*

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


## Features

- Cruise control
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim

## Photos












## Condition Check



## Damage Photos



1: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



2: Door osf  
Dented  
With Paint Damage



3: Bonnet  
Chipped  
Multiple Chips



4: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



5: Door osf  
Scratched  
Over 25mm Thru Paint



6: Door Pad osf  
Soiled  
Heavy



7: Seat Base Cover osf  
Torn  
Over 3mm

## Interior

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	Poor
<b>Seat Condition</b>	Poor	<b>Odour</b>	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		