

VEHICLE INSPECTION REPORT

C355311

DON BUR BOX

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2013	Colour	RED	Brakes	Disc
Year	2013	VIN	SEPBV38GKDL061810	Axle Combi	Tri
Mileage	TBC	Body Style	Trailer	Rear Doors	Roller
Fuel Type		MOT Due	31/10/2025		

CORROSION BPW AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF
NSR
OSF
OSR
Spare