

# VEHICLE INSPECTION REPORT

**DG16DVX**

## Man TGS 26.360

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date	23/05/2016	VIN	WMA18SZZ7GW214200	Axle Combi	6x2
Year	2016	Body Style	Curtainside	Steering Combi	Rear-Lift Steer
Mileage	424,536 Km Warranted	MOT Due	31/05/2026	Rear Suspension	Steel
Fuel Type	Diesel	Cab Type	DAY CAB	Rear Doors	Barn
Colour	BLUE	Gearbox	MANUAL		

FORKLIFT BRACKETS, SURROUND CAMERA SYSTEM, SERVICE SCHEDULE LIST AVAILABLE


### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


## Features

- Park assist camera

## Photos










## Condition Check



## Damage Photos



1: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



2: Fog Lamp Surround as  
Scuffed (Unpainted)  
Over 100mm



3: Wing osf  
Chipped  
Multiple Chips



4: Bumper Front  
Scratched  
UpTo 25mm Not Thru Paint



5: Bonnet  
Chipped  
Multiple Chips



6: Screen Front  
Chipped  
Over 10mm



7: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



8: Fog Lamp Surrounds  
Scuffed (Unpainted)  
UpTo 100mm





9: Wing nsf  
Chipped  
Multiple Chips



10: Door Mirror Assy nsf  
Missing  
Replace



11: Door Mirror Assy nsf  
Scuffed (Unpainted)  
UpTo 100mm



12: Other  
N/A  
N/A



13: Other  
N/A  
N/A



14: Bumper Rear  
Rusted  
Over 5mm





15: Other  
N/A  
N/A



16: Other  
N/A  
N/A



17: Door osf  
Scratched  
UpTo 25mm Thru Paint



18: Door osf  
Chipped  
Edge Chip



19: Other  
N/A  
N/A



20: Door Mirror Assy osf  
Scuffed (Unpainted)  
UpTo 100mm



21: Seat Base Cover osf  
Holed  
Over 3mm

22: Other  
N/A  
N/A

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Parking Brake	OK			Gearbox Static Gear Selection (engine running)	OK		
				No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		