

# VEHICLE INSPECTION REPORT

**NL69ETU**

## Scania G 450

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date 01/11/2019

Year 2019

Mileage 1,076,256 Km  
Warranted

Fuel Type Diesel

Colour WHITE

VIN YS2G6X20005567829

Body Style Tractor Unit

MOT Due 30/11/2025

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

### SLIDING 5TH WHEEL

### Tyres

NSF NSI1

OSF OSI1

Spare NSO1

NSI2

OSI2

NSO2

NSI3

OSI3

NSO3

NSI4

OSI4

NSO4

## Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Auxiliary input socket
- Central locking
- Digital radio
- Cloth seat trim

## Photos












## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Door Mirror Assy nsf  
Broken  
Replace



3: Door osf  
Scratched  
Over 25mm Thru Paint



4: Screen Front  
Cracked  
Replace

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		OK	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			