

VEHICLE INSPECTION REPORT

PE65UZU

Daf LF 220

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	04/11/2015	VIN	XLRAEL3700L448388	Cab Type	DAY CAB
Year	2015	Body Style	Box Van	Gearbox	AUTOMATIC
Mileage	565,825 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Printout	Rear Suspension	Steel
Colour	RED	MOT Due	31/03/2026	Tail Lift	Cantilever

*COLLECTED AS NON RUNNER - ENGINE/ TURBO ISSUES**WARNING LIGHT ON DASH*

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Door Pad osf
Soiled
Heavy



2: Dash Warning Lights
Displayed
No Action

Interior

Carpets Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK

EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		