

VEHICLE INSPECTION REPORT

C338819

DON BUR BOX DOUBLE DECK

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	31/12/2013	Colour	RED	Brakes	Drum
Year	2013	VIN	SEPBV38GHDL060776	Axle Combi	Tri
Mileage	TBC	Body Style	Trailer	Rear Suspension	Air
Fuel Type		MOT Due	30/06/2026	Rear Doors	Roller

* DECK SLIDERS REQUIRE ATTENTION*, BPW AXLES, FERRY LASHING RINGS

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



